Seattle
Department of Construction and Land Use

February 8, 1990

Re: Passenger Elevators #3835 & 3836

At: Regency Motor Inn
2200 - 5th Avenue
Inspected: December 28, 1989

Regency Motor Inn
Attn: Manager
2200 - 5th Avenue
Seattle, WA 98121

The Seattle Elevator Ordinances Nos. 113700 and 113701, and the Washington State Elevator Code establish certain safety standards for the installation and operation of conveyances within the City. Inspection of the subject conveyances indicates the following corrections must be made:

1. In any building with more than one elevator, a designating number, not less than 2 inches in height, shall be placed over the door of the main entrance lobby, inside the car, on the machine and on the disconnect switch. [S-5111.(dd)]

Car #2:
2. Correctly wire the cartop convenience outlet.

Your response is required to be in this office not more than 30 days from the date of this report.

DENNIS McLERRAN
DIRECTOR

by Robert P. Bruker

Robert Bruker
Elevator Inspector
684-8454

RB:pw E020809