

Seattle  
Department of Construction and Land Use



Holly Miller, Director  
Charles Royer, Mayor

June 13, 1988

RE: Passenger Elevator #'s 3835 & 3836  
At: 2200 5th Avenue  
Permit Month: November  
Inspected: June 10, 1988

Regency Motor Inn  
2200 5th Avenue  
Seattle, WA 98121

The Seattle Elevator Ordinance No. 111200 and the Washington State Elevator Code establish certain safety standards for the installation and operation of conveyances within the City. Inspection of the subject conveyances indicates the following corrections must be made:


1. Modify the machine room door lock to prevent the lock from being able to be left in the unlocked position from the hall side and remain operable from inside the machine room.
2. Car #1 Make the emergency light unit and alarm bell operable.
3. Turn down all fire tabs on all door gibs in the hoistway and on the car.

Both cars

4. S-5111.26. A toggle-type test switch shall be provided on the top of the car to cut lighting power manually and test the emergency lighting and alarm bell.
5. S-5111.16. Floor Numbers. Elevator hoistways shall have floor numbers, not less than 2 inches in height, placed on the walls and/or doors of hoistways at intervals where a person in a stalled elevator upon opening the car door can determine the floor position.

Please notify this department by letter within thirty (30) days when the above correction(s) will be or have been completed.

HOLLY MILLER  
Director

By:   
ROBERT DENNIS  
City Elevator Inspector  
684-8455  
RD:bc