



Department of Planning  
& Development  
ELEVATOR SECTION  
700 Fifth Avenue, Suite 2000  
P.O. Box 34019  
Seattle, WA 98124-4019

City of  
**SEATTLE**  
Conveyance Inspection Report

Site No.  
82039

Printed	Page
10/27/2005	Page 206 of 231
Customer #	District
0040054	9
# of Conveyances	
2	
Inspector	Inspection Date
<del>MAR</del> = <i>Bill</i>	12-16-05

Site Address	Billing Address
BANK OF AMERICA TUNNEL 800 5TH AVE SEATTLE, WA 98104	Bank Of America Tower EOP/Columbia Center LLC 701 5th Av #4040 Seattle, WA 98104 (206) 386-5177

Contact Name	Contact Phone	Special Instructions
--------------	---------------	----------------------


See Comments below

Service Company: *OTIS*

City No Owner #	Manufacturer/Type Mach Room Location	Cap Speed	Stops # Open	Rise Code	CTI	KACC PDOR	PACC SPSS	PHI/II KEY	Signal	Stat Var	5-Year	Accepted Last Insp	Seis mic
5064 #1-P	OTIS/PASSENGER ELEVATOR/ BASEMENT - PARK GARAGE	2500	2 2	2020	Y	Y	LL Y	YY GB	<i>ADA - Phone INTER-com Bell</i>	A N	11/1/01	3/27/86 12/9/04	<i>U N</i>
5065 #2-P	OTIS/PASSENGER ELEVATOR/ BASEMENT - PARK GARAGE	2500	2 2	2020	Y	Y	LL Y	YY GB	<i>ADA - Phone Intercom Bell</i>	A N	11/1/01	3/27/86 12/9/04	<i>U N</i>

Comment Type	Comment
Informational	12/02 L2

*L1  
All ELEVATORS  
1) TEST & TAG ELEVATOR machine ROOM FIRE EXTINGUISHERS  
2) 5 YEAR SAFETY TEST ARE DUE NEXT YEAR.  
L21*



COMMENTS: