



City of Seattle

Gregory J. Nickels, Mayor

Department of Planning and Development

Diane M. Sugimura, Director

February 23, 2006

Seattle University
Facilities Operation
901 12th AV
Seattle, Washington 98122

Re: Passenger Elevator #5976
At: 1001 E Madison ST – Fine Arts Bldg
Inspected: February 14, 2006

Our inspection indicates the following corrections must be made for the elevator equipment at this site to meet the current safety standards:

1. Repair the elevator machine room door so the latch will not stick in the open position.
2. The shunt trip is powered from a source outside the elevator machine room. This required the shunt trip interface box to be labeled with the circuit breaker number and the panel ID. The shunt trip interfaces box also needs an indicator light to show that the power is on and labeled for its function. (Label should read shunt trip power indicator)

Please notify this Department by letter, within 30 (thirty) days, when the above correction(s) have been completed.

Sincerely,

Bud Bir
Elevator Inspector
206-684-8457

BB:sd E83740



City of Seattle, Department of Planning and Development
700 Fifth Avenue, Suite 2000
P.O. Box 34019
Seattle, WA 98124-4019

An equal employment opportunity, affirmative action employer. Accommodations for people with disabilities provided upon request.