



CITY OF
SEATTLE
REPORT OF INSPECTION

Department of Design,
 Construction & Land Use
Elevator Section
 700 Fifth Ave, Suite 2000
 Seattle, WA 98104-5070

Location: Key Tower, 22nd Floor

SITE ADDRESS		OWNER OR AGENT		SITE NO.	MONTH
ANTIQUE LIQUIDATORS 00503 WESTLAKE AV N SEATTLE, WA 98109		Antique Liquidators Carl Smith 503 Westlake Av N Seattle, WA 98109		3823	7
SITE CONTACT PHONE				PAGE	AREA
Mgmt/Owner MATT OR CARL SMITH Maintenance () 623-2740		Billing Phone: (206) 623-2740 Customer_Key: 0080704		Page 168 / 300	4
				# OF CONV/INSP	PRINTED
				1	5/29/2003
SPEC. INST.				DATE	INSP
				7-14-03	SKALA

WARNING - CRITICAL CONDITIONS - OTHER

CITY NO OWNER #	CONVEYANCE MRF/MACH/TYP MACH ROOM LOCATION	CAP SPEED	STOPS # OPEN	RISE CODE	CTI	KAC	PACC	PHI/II KEY	SIGNAL	STAT VAR	5-YEAR PAY NO	ACCEPTED LAST INSP	PD
F-821 #1-F	OTIS ROOF	5000 50	4 5	30' 103	Y AC	N N	LL Y	N N NON	ALARM BELL	A N	5/2/1990 0080704	4/25/1973 7/2/2002	
<p style="text-align: center;">W</p> <p>1- Replace the loose door lock latch on the rear alley hoistway door. Note: the latch is too thick for the lock and does not engage properly into the locks.</p> <p>2- ELOC.</p> <p style="text-align: center; font-size: 2em;">L21</p>													

COMMENTS:
 3/30/00 L2



CONTINUED ON BACK