



Department of Planning
& Development
ELEVATOR SECTION
700 Fifth Avenue, Suite 2000
P.O. Box 34019
Seattle, WA 98124-4019

City of
SEATTLE
Conveyance Inspection Report

J

Site No
84293

Printed: 12/2/2008 Page: Page 320 of 322
Customer #: DPD0081648 District: 11
of Conveyances: 1
Inspector: HOLMAN Inspection Date: 11/14/09


Site Address	Billing Address
NORTHERN TRUST BANK 1414 4TH AVE SEATTLE, WA 98101-	NORTHERN TRUST BANK Rose Holifield 1414 4TH AV SEATTLE WA 98101

Contact Name: ROSE HOLIFIELD Contact Phone: 206-264-8000 Special Instructions: See Comments below

Service Company:

City No Owner #	Manufacturer/Type Mach Room Location	Cap Speed	Stops # Open	Rise Code	CTI	KACC PDOR	PACC SPSS	PH/MI KEY	Signal	Stat Var	5-Year	Accepted Last Insp	Seis mic
7302	OTIS/PASSENGER ELEVATOR/	2000	2	11'2"	Y	N	LL	YY	Phone, Bell, Intercom	A		11/12/99	U
1	ADJ 1ST FLOOR	100	2	0060		Y	Y	BKARM		N		1/18/08	

Comment Type	Comment
Informational	02/04 L2. 03/04 PREV. SITE ADDRESS 1420 02/07 L2



ENTERED

COMMENTS: R/V 10/08