



**CITY OF  
SEATTLE  
REPORT OF INSPECTION**

Department of Design,  
Construction & Land Use  
**Elevator Section**  
700 Fifth Ave, Suite 2000  
Seattle, WA 98104-5070

Location: Key Tower, 22nd Floor

<b>SITE ADDRESS</b>		<b>OWNER OR AGENT</b>				<b>SITE NO.</b>	<b>MONTH</b>
WOMEN'S UNIVERSITY CLUB 01105 6TH AV SEATTLE, WA 98101		WOMEN'S UNIVERSITY CLUB Executive Manager 1105 6TH AV SEATTLE WA 98101				4097	5
<b>SITE CONTACT</b>		<b>PHONE</b>				<b>PAGE</b>	<b>AREA</b>
Mgmt/Owner ADMINISTRATOR Maintenance ( ) 623-0402				Billing Phone: (206) 623-0402 Customer_Key: 0040313		Page 117 / 240	5
						<b># OF CONV/INSP</b>	<b>PRINTED</b>
						2	4/8/2003
<b>SPEC. INST.</b>	CITY KEYBOX #2 ELEV.			<b>DATE</b>	4-28-03	<b>INSP</b>	MCANNA

**WARNING - CRITICAL CONDITIONS - OTHER**

CITY NO OWNER #	CONVEYANCE MRF/MACH/TYP MACH ROOM LOCATION	CAP SPEED	STOPS # OPEN	RISE CODE	CTI DRV	KACCP PDOR	PACC PSS	PHI/II KEY	SIGNAL	STAT VAR	5-YEAR PAY NO	ACCEPTED LAST INSP	PD
P-2772 #1-P	DOVER	2200	6 6	5	Y AC	N Y	LL Y	N N GAL	ALARM BELL	A	0040313	12/28/1964 5/29/2002	
P-4666 #2-P	DOVER	2000	5 5	5	Y AC	N Y	LL Y	Y Y GAL	PHONE	A	0040313	1/4/1983 5/29/2002	

**COMMENTS:** L1  
05/02 L2  
Car # 2  
1. Empty oil bucket in p.T.  
2. No machine room inspection as no keys available.  
3. M33 a



CONTINUED ON BACK

